

HARDWARE AUDIT REPORT



DOCUMENT INFO

DOCUMENT ID:	427298885	OPERATOR:	test
REPORT DATE:	11.10.2017 11:07:55 (+00:00)	SOFTWARE VERSION:	3.10.3
REMARKS:			

SYSTEM HARDWARE INFORMATION

MANUFACTURER:	Acer	SERIAL NUMBER:	LXPK70X0099341BDDA2000
CHASSIS TYPE:	Other	MOTHERBOARD:	Acer; Aspire 5810T
MODEL:	Aspire 5810T	UUID:	802D13A4-5592-DE11-909B-CE1EC5F6E754
BIOS:	INSYDE; Version: V1.28.; Release date: 08/17/2009		
PROCESSOR:	Intel(R) Corporation; Family: Pentium M; Version: Genuine Intel(R) CPU U4100 @ 1.30GHz; Frequency: 1200MHz		
MEMORY SLOT 1:	0198; 2048 MB; Current 1 ns; SODIMM; None - Synchronous		
MEMORY SLOT 2:	0198; 2048 MB; 800 MHz; SODIMM; Unknown - Synchronous		
MEMORY INFO:	Total Memory: 4 GB; Number of memory slot: 2		
GRAPHICS CARD 1:	Intel Corporation Mobile 4 Series Chipset Integrated Graphics Controller		
GRAPHICS CARD 2:	Advanced Micro Devices, Inc. [AMD/ATI] RV710/M92 [Mobility Radeon HD 4330/4350/4550]		
SOUND CARD 1:	Intel Corporation 82801I (ICH9 Family) HD Audio Controller		
SOUND CARD 2:	Advanced Micro Devices, Inc. [AMD/ATI] RV710/730 HDMI Audio [Radeon HD 4000 series]		
NETWORK ADAPTER 1:	Qualcomm Atheros AR8131 Gigabit Ethernet; 00:1F:16:B7:D3:20		
NETWORK ADAPTER 2:	Intel Corporation Centrino Wireless-N 1000 [Condor Peak]; 00:1E:64:05:16:38; 172.16.0.28; 172.16.0.1; 255.255.0.0		
OPTICAL DRIVE:	MATSHITA; Model: DVD-RAM UJ862AS; Revision: 1.00		
STORAGE CONTROLLER:	Intel Corporation 82801IBM/IEM (ICH9M/ICH9M-E) 4 port SATA Controller [AHCI mode]		
STORAGE DEVICE:	Toshiba; TOSHIBA MK5055GSX; 500 GB/976773168; HDD; SATA; Sector-size:512; HPA: Disabled; DCO: Disabled; Remapped sectors:384		
PERIPHERAL PORTS:	Unknown		
BATTERY:	Panasonic; Model: AS09D56; Serial: 19395; Technology: Li-ion; Energy design: 5800 mAh; Life: 86.00 %		